

Under Review Notification

Raised By: Steven Drouin

Date: 18/10/02

Product #: D130-780 / D139-799

Product Name: Space pod / Maintenance kit

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	Parts Under Review	Product Specifications Under Review ("Bluefiles")		
D130-780-043	IIN-D130-780 Rev. B	Y	Y	N	Y	Y	Y	Y	18-820	CHG #002
D130-780-044	IIN-D130-780 Rev. B	Y	Y	N	Y	Y	Y	Y	18-820	CHG #002
D139-799-013	IIN-D139-799 Rev. O	Y	Y	N	Y	Y	Y	Y	18-820	CHG #007
D5275-1/041	D5275 Rev. A	Y	Y	N	Y	Y	Y	Y	18-820	Design Change

Description of Issue:

Stop production for the following parts until further notice from Engineering

Customer Support: Advise existing customer with the new design change created by engineering

REASON : The door latch (D5275) falls apart when a high stress level occurs at rivet location in the latch. REF CAR18-251

Distribution:

VP Operations

Director of Operations

Director Quality Assurance

QC Coordinator

Director of Engineering

Chief Engineer

Engineering Project Managers

Engineering Clerk

Customer Support Manager

Production Engineers

Production Planners

Purchasing Manager

Technical Support

Product Manager - Solutions Provider

Supply Chain Director

Marketing Eugene